

FIG. 1

Default - NETGEAR MA401 802.11... X

Status | About

Status: Associated - 00:09:5B:2A:79:7E

Current Channel: 10 Rescan

Current Tx Rate: 11 Mbits/sec Disable Radio

Throughput (Bytes/sec)

Tx: 28 Rx: 506

Signal Strength: Poor (13%)

■■■■

Link Quality: Poor (6%)

■■

OK Cancel Apply

FIG. 2A

Default - NETGEAR MA401 802.11... X

Status | About

Status: Associated - 00:09:5B:2A:79:7E

Current Channel: 10 Rescan

Current Tx Rate: 11 Mbits/sec Disable Radio

Throughput (Bytes/sec)

Tx: 0 Rx: 640

Signal Strength: Fair (46%)

Link Quality: Fair (46%)

OK Cancel Apply

FIG. 2B




FIG. 3




FIG. 4C




FIG. 4B




FIG. 4A




FIG. 4D




FIG. 4E




FIG. 5A




FIG. 5D




FIG. 5B




FIG. 5C









FIG. 6








FIG. 9A




FIG. 9B




FIG. 10A




FIG. 10B




FIG. 10C




FIG. 10D




FIG. 11A




FIG. 11B




FIG. 11C




FIG. 11D




FIG. 11E




FIG. 11F




FIG. 12A




FIG. 12B




FIG. 13A




FIG. 13B




FIG. 14




FIG. 15





FIG. 16





FIG. 17






FIG. 18B